MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA+20)

DATE OF PREP 10 - 81

Section I

BOSTIK WEST, DIV. OF USM CORPORATION, AN EMHART UNIT MANUFACTURER'S NAME

STREET ADDRESS 20846 So. Normandie Ave. CITY, STATE, AND ZIPCODE Torrance, Ca. 90502

EMERGENCY TELEPHONE NO. (213) 320-6800

PRODUCT CLASS

AMINE ABDUCT.

TRADE NAME

BOSTIK

MANUFACTURERS CODE IDENTIFICATION

CA-118

Catalyst for: 453-3-Series, 463-3-Series

463-3-8, 454-3-Series. Mix Ratio: 3 parts

Base to 1 part CA-118 by volume.

Section II — HAZARDOUS INGREDIENTS

INGREDIENT CA-118 Epoxy Catalyst	CAS No.	PERCENT (Wt.)	PPM	LV mg/M³	LEL	VAPOR PRESSURE IIIII Hg.
Methyl ethyl ketone	78-93-3	25-30	200		1.8	70.0
Butyl alcohol	71-36-3	20-25	100		1.7	4.0
Butyl acetate -	123-86-4	20-25	150		1.7	8.0
Butyl cellosolve	111-76-2	10-15	50		1.1	1.0
Toluene	108-88-3	< 5.0	200		1.2	22.0
Diethylenetriamine(DETA)	111-40-0	Trace	1.0		1.4	< 1.0
·		·		,		
4						

Section III — PHYSICAL DATA

	·				
BOILING RANGE	176-340° F.	VAPOR D	ENSITY	X HEAVIER	LIGHTER, THAN

EVAPORATION RATE

FASTER

SLOWER, THAN ETHER

PERCENT VOLATILE BY VOLUME

WEIGHT PER GALLON

7.0 lbs.

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY

Red Label, Flammable

(Min) FLASH POINT

23° F. Tag Closed Cup

LEL 1.1

AIR

EXTINGUISHING MEDIA

Exclude air - Use foam, CO_2 , steam, water fog,

87%

dry chemicals. Do not use water.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Vapor forms explosive mixture with air between

upper and lower explosion limits.

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water, exclude air, use water spray to cool fire exposed surfaces and to protect personnel.

Section V — HEALTH HAZARD DATA
THRESHOLDLIMIT VALUE: See Section II EFFECTS OF OVEREXPOSURE: Headache, nausea, dizziness. Breathing vapor will be irritating to nose, throat, and eyes.
Emergency and first aid procedures: Skin Exposure: Wash affected area with soap and water. Eye Exposure: Flush with water for at least 15 minutes, consult physician. Ingestion: Consult physician immediately. Inhalation: Remove victim to fresh air., consult physician.
Section VI — REACTIVITY DATA
Incompatability (Materials to avoid): Strong oxidizing agents. Sparks & open flame Hazardous Decomposition Products: On combustion CO, CO2, Aldehydes and other organics, oxides of nitrogen. HAZARDOUS POLYMERIZATION MAYOCCUR XXX WILL NOT OCCUR
Section VII — SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Eliminate sources of ignition and clear fumes from area Prevent liquid from entering sewers, water sources, or low areas. Keep unnecessary personnel away Shut off source, if possible to do so without hazard. Contain spilled liquid with sawdust, sand or Waste Bisposal Method of Mash area with detergent & water. Consult disposal expert and ensure conformity with local regulations.
Section VIII — SPECIAL PROTECTION INFORMATION
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mask if used in non-ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.
VENTILATION : Face velocity $>$ 60 fpm in confined area
Protective Gloves: Chemically resistant gloves. EYE PROTECTION: Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT: Eye bath & Safety Shower.
Section IX — SPECIAL PRECAUTIONS PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use. Do No handle or store near flame, heat or strong oxidants. Adequate ventilation required. Containers of this product may be hazardous when emptied - these containers retain product residues (vapor, liquid, etcother precautions
All handling equipment should be electrically grounded. Treat as a very flammable liquid.

Lee A. Dickinson Technical Service Manager